



DueList Report

FALCON 900

S/N 075 C-GEOS

OWNER: ROMMEL AVIATION GP INC.
ADDRESS: C/O PARAMOUNT RESOURCES LTD.
CALGARY AB T2P 4K9
OFFICE:
FAX:

OPERATOR: SKYSERVICE BUSINESS
AVIATION INC.
ADDRESS: SKYSERVICE BUSINESS AVAITION
INC
CALGARY AB T2E 7G4
OFFICE: 403-592-3729
FAX: 403-769-1522

ANALYST: BRIANNA SALADINO
EMAIL: BSALADINO@CAMPSYSTEMS.COM

631-619-4523 (DIRECT)
800-787-9749 (EFAX-CARDS)
+1-631-588-3200 (MAIN)
631-980-4222 (FAX)
WWW.CAMPSYSTEMS.COM

PROJECTED: 24 MOS. to 16-JAN-2027

AIRCRAFT SERIAL/REGNO: 075/C-GEOS MODEL: FALCON 900 MANUFACTURER: DASSAULT AVIATION S.A.

CERTIFICATION DATE: 23-OCT-1989
LAST ACTUALS: PROJECTED:
9977.7 A/C HRS as of 16-JAN-2025 10457.70
4686 AFL as of 16-JAN-2025 4926
5700.8 APH as of 20-DEC-2024 6181

APU SERIAL/PART: P-183/3800188-1 MODEL: GTCP36-150(F) MANUFACTURER: HONEYWELL

INSTALLED ON: 27-MAY-2004
LAST ACTUALS: PROJECTED:
3160.5 APU HRS 4847.4 A/C HRS 5700.8 APU HRS as of 20-DEC-2024 6180.80
0 APUS as of 17-DEC-2024 0

ENGINE NO. 1 SERIAL/PART: P-97290C/3075330-3 MODEL: TFE731-5BR-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 10-MAR-2014
LAST ACTUALS: PROJECTED:
7781.8 ENG. HRS 8005.9 A/C HRS 9753.6 ENG. HRS as of 16-JAN-2025 10233.60
3851 ENC as of 16-JAN-2025 4940

ENGINE NO. 2 SERIAL/PART: P-97289C/3075330-3 MODEL: TFE731-5BR-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 19-JUN-2014
LAST ACTUALS: PROJECTED:
8005.9 ENG. HRS 8032 A/C HRS 9951.6 ENG. HRS as of 16-JAN-2025 10431.60
3957 ENC as of 16-JAN-2025 5198

ENGINE NO. 3 SERIAL/PART: P-97291C/3075330-3 MODEL: TFE731-5BR-1C MANUFACTURER: HONEYWELL

INSTALLED ON: 20-JUN-2012
LAST ACTUALS: PROJECTED:
7478.7 ENG. HRS 7663.6 A/C HRS 9792 ENG. HRS as of 16-JAN-2025 10272
3696 ENC as of 16-JAN-2025 4933
0 (AFL) as of 08-AUG-2024 720



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
990000 <sup>U</sup> <b>PERFORM 30 DAY REVIEW AIRWORTHINESS DIRECTIVES</b>									
	DAYS	30	16-Dec-24		15-Jan-25 (M)		OVD		Service ATA:99 31 d
	HRS								
	AFL								
REF:									
54-00-00-210-811-01 <b>GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE</b>									
	MOS		15-Feb-23					23-Jan-2025(2)	Service ATA:54 23
	HRS	300 (+100)	9683.1	Adj:-.3	9982.8	10082.8	5.1 (+100)		294.6
	AFL		4588						98
REF: AMM 54-00-00-210-811									
SB TFE731-72-3494 R13 <b>NO. 3 ENGINE - TURBINE SECTION - HIGH PRESSURE (HP) AND LOW PRESSURE (LP) TURBINE BLADE HOUR TRACKING AND RECOMMENDED BLADE REPLACEMENT INTERVALS FOR TFE731-2, -3, -4, -5 SERIES ENGINE MODELS, SERVICE BULLETIN</b>									
	MOS	MPI	21-Jun-23		23-Jan-25 (M)		7 d	23-Jan-2025	Bulletin ATA:72 18.8
	HRS		9618.13		(9978.7)10164.4 (M)		186.7		173.87
	ENC		4615						-42
Disposition: CATEGORY 2      REF: BULLETINS									
057120 <b>NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION</b>									
	MOS		15-Feb-23					24-Jan-2025(2)	Package ATA:05 23
	HRS	300 (+100)	9459		(9759)9983.1	9859	5.4 (+100)		294.6
	ENC		4482						98
REF: LMM 72-00-00									
057120 <b>NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION</b>									
	MOS		15-Feb-23					24-Jan-2025(2)	Package ATA:05 23
	HRS	300 (+100)	9657		(9957)9983.1	10057	5.4 (+100)		294.6
	ENC		4580						258
REF: LMM 72-00-00									
057120 <b>NO. 3 ENGINE - 300 TO 400 HOUR INSPECTION</b>									
	MOS		15-Feb-23					25-Jan-2025(2)	Package ATA:05 23
	HRS	300 (+100)	9498.2		(9798.2)9983.9	9898.2	6.2 (+100)		293.8
	ENC		4475						98
REF: LMM 72-00-00									
28-30-00-680-803-01 <b>DRAINING OF THE GRAVITY DEFUELING LINE</b>									
	MOS	2 (+5d)	28-Nov-24		28-Jan-25	02-Feb-25	12 d (+5)	28-Jan-2025(12)	Service ATA:28 1.6
	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 28-30-00-680-803									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS&#13;&#10;							
	MOS	2 (+5d)	28-Nov-24		28-Jan-25	02-Feb-25	12 d (+5)	28-Jan-2025(12)	1.6
	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 28-30-00-680-804									
32-44-00-780-801-01		PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES							
	MOS	2 (+5d)	28-Nov-24		28-Jan-25	02-Feb-25	12 d (+5)	28-Jan-2025(12)	1.6
	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 32-44-00-780-801									
SI-05-001 <sup>U</sup>		CABIN SAFETY & EMERGENCY EQUIPMENT INSPECTION&#13;&#10;							
	MOS	6 (+30d/-30d)	31-Jul-24		31-Jan-25	02-Mar-25	15 d (+30)	31-Jan-2025(4)	5.5
	HRS								
	AFL								
REF:									
SI-05-002 <sup>U</sup>		VISUALLY INSPECT INTERIOR AND EXTERIOR PLACARDS AND MARKINGS IAW SI-05-002 AT ITS LATEST REVISION							
	MOS	6 (+30d)	31-Jul-24		31-Jan-25	02-Mar-25	15 d (+30)	31-Jan-2025(4)	5.5
	HRS		9890.4						87.3
	AFL		4657						29
REF:									
23-CARS-625-016-05 <sup>U S</sup>		CVR ULB BATTERY REPLACEMENT&#13;&#10;							
	MOS		20-May-21		01-Feb-25 (M)		16 d	01-Feb-2025	43.9
REF:									
25-62-05-960-801-01		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - CVR ULB BATTERY (900RK1)							
PN:DK120	MOS	DUE	04-Apr-24		01-Feb-25 (M)		16 d	01-Feb-2025	9.4
SN:SD17225	HRS		9887						90.7
	AFL		4656						30
Disposition: LIFE LIMIT REF: AMM 25-62-05-960-801									
SI-05-008 <sup>U</sup>		PERFORM VERIFICATION OF ACCURACY OF COMPUTERIZED MAINTENANCE TRACKING SYSTEM IAW SKYSERVICE SPECIAL INSPECTION SI-05-008 AT ITS LATEST REVISION							
	MOS	3 (+7d/-7d)	17-Dec-24	Adj: -31d	14-Feb-25	21-Feb-25	29 d (+7)	14-Feb-2025(8)	1
	HRS		9952.1						25.6
	AFL		4678						8
REF:									
28-21-14-720-801-01		FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 1 MANIFOLD (32WB1)							
PN:L88A31-662	MOS		23-Oct-89					18-Feb-2025	422.8
SN:20120	HRS	10000 (+3%)	0		10000	10300	22.3 (+300)		9977.7

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
	AFL		0						4686
REF: AMM 28-21-14-720-801									
28-21-14-720-801-03 FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 3 MANIFOLD (32WB3)									
PN:L88A31-664	MOS		23-Oct-89					18-Feb-2025	422.8
SN:20127	HRS	10000 (+3%)	0		10000	10300	22.3 (+300)		9977.7
	AFL		0						4686
REF: AMM 28-21-14-720-801									
761A07 <sup>U</sup> DOWNLOAD NO. 1 ENGINE DEEC ECTM									
	MOS		28-Nov-24					18-Feb-2025(10)	1.6
	HRS	50	9949.8		9999.8		22.1		27.9
	AFL		4676						10
REF:									
761A08 <sup>U</sup> DOWNLOAD NO. 2 ENGINE DEEC ECTM									
	MOS		28-Nov-24					18-Feb-2025(10)	1.6
	HRS	50	9949.8		9999.8		22.1		27.9
	AFL		4676						10
REF:									
761A09 <sup>U</sup> DOWNLOAD NO. 3 ENGINE DEEC ECTM									
	MOS		28-Nov-24					18-Feb-2025(10)	1.6
	HRS	50	9949.8		9999.8		22.1		27.9
	AFL		4676						10
REF:									
S1-05-001R14 <sup>U</sup> PERFORM CABIN SAFETY AND EMERGENCY EQUIPMENT INSPECTION									
	MOS	6 (+30d)	21-Aug-24		21-Feb-25	23-Mar-25	36 d (+30)	21-Feb-2025(4)	4.8
	HRS		9894.2						83.5
	AFL		4658						28
REF:									
33-50-37-960-802-01 DISCARD OF THE EPS BATTERY PACKS - EPS 1 (L3LW) BATTERY PACK									
PN:C734-01-030	MOS	25	31-Jan-23		28-Feb-25		43 d	28-Feb-2025	23.5
SN:CF34768/14/22	HRS		9660.2						317.5
	AFL		4580						106
Disposition: LIFE LIMIT REF: AMM 33-50-37-960-802									
25-CARS-625-012-05 <sup>U</sup> FUNCTIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM IAW APP G OF STD 571									
	MOS	24	02-Mar-23		02-Mar-25		45 d	02-Mar-2025	22.5
	HRS								
	AFL								
Disposition: CARS REF:									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
256A76 <sup>U</sup>		RECERTIFY EMERGENCY LOCATOR (ELT) TRANSMITTER							Service	ATA:25
PN:453-5000-316	MOS	12	03-Mar-23		02-Mar-25 (M)		45 d	02-Mar-2025	22.4	
SN:02103	HRS		9687.8						289.9	
	AFL		4590						96	
REF:										
32-10-00-640-801-01		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND DOORS							Service	ATA:32
	MOS	8 (+1m)	08-Aug-24	Adj: -37d	02-Mar-25	02-Apr-25	45 d (+31)	02-Mar-2025(3)	5.3	
	HRS		9890.4						87.3	
	AFL	400	4657		5057		371		29	
REF: AMM 32-10-00-640-801										
32-10-00-640-801-02		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND DOORS							Service	ATA:32
	MOS	8 (+1m)	08-Aug-24	Adj: -37d	02-Mar-25	02-Apr-25	45 d (+31)	02-Mar-2025(3)	5.3	
	HRS		9890.4						87.3	
	AFL	400	4657		5057		371		29	
REF: AMM 32-10-00-640-801										
32-20-00-640-801-01		LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG LEG (3GF)							Service	ATA:32
	MOS	8 (+1m)	08-Aug-24	Adj: -37d	02-Mar-25	02-Apr-25	45 d (+31)	02-Mar-2025(3)	5.3	
	HRS		9890.4						87.3	
	AFL	400	4657		5057		371		29	
REF: AMM 32-20-00-640-801										
25-CARS-625-012-00 <sup>U</sup>		OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM IAW APP G OF STD 571							Service	ATA:25
	MOS	12	08-Mar-24		08-Mar-25		51 d	08-Mar-2025(2)	10.3	
	HRS		9873.8						103.9	
	AFL		4652						34	
Disposition: CARS										
REF:										
24-31-17-220-805-01		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 1 STARTER-GENERATOR (L1PA)							Service	ATA:24
PN:8060-160	MOS		15-Feb-24					17-Mar-2025(3)	11	
SN:2024	HRS	150	9867.5		10017.5		39.8		110.2	
	AFL		4649						37	
REF: AMM 24-31-17-220-805										
23-CARS-625-015-00 <sup>U</sup>		CVR FUNCTIONAL / INTELLIGIBILITY CHECK							Service	ATA:23
	MOS	12	04-Apr-24		04-Apr-25		78 d	04-Apr-2025(2)	9.4	
	HRS	3000	9887		12887		2909.3		90.7	
	AFL		4656						30	
REF:										



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
<b>23-CARS-625-015-06<sup>U</sup> FUNCTIONAL CHECK OF RECORDER INDEPENDENT POWER SUPPLY (RIPS)</b>									
	MOS	12			04-Apr-25 (M)		78 d	04-Apr-2025	Service ATA:23
	HRS	3000			12887 (M)		2909.3		
	AFL								
Disposition: CARS REF:									
<b>23-CARS-625-016-00<sup>U</sup> CVR ULD RECERTIFICATION&amp;#13;&amp;#10;</b>									
	MOS	12	04-Apr-24		04-Apr-25		78 d	04-Apr-2025(2)	Service ATA:23
	HRS		9887						9.4
	AFL		4656						90.7
									30
REF:									
<b>315A15<sup>U</sup> RECERTIFY VOICE DATA RECORDER UNDERWATER LOCATOR BEACON</b>									
PN:DK120	MOS	12	04-Apr-24		04-Apr-25		78 d	04-Apr-2025(2)	Service ATA:31
SN:SD17225	HRS		9887						9.4
	AFL		4656						90.7
									30
REF:									
<b>315A16<sup>U</sup> PERFORM VOICE DATA RECORDER FUNCTION AND INTELLIGIBILITY TEST</b>									
PN:1601-02-3	MOS	12	04-Apr-24		04-Apr-25		78 d	04-Apr-2025(2)	Service ATA:31
SN:6105	HRS	3000	9887		12887		2909.3		9.4
	AFL		4656						90.7
									30
REF:									
<b>231A15<sup>U</sup> CHECK COMMUNICATION STAND-BY BATTERY CHARGE</b>									
PN:501-1228-04	MOS	6	11-Oct-24		11-Apr-25		85 d	11-Apr-2025(4)	Service ATA:23
SN:2123A	HRS		9913						3.2
	AFL		4664						64.7
									22
REF:									
<b>342A15<sup>U</sup> CHECK STAND-BY HORIZON BATTERY CHARGE</b>									
PN:501-1228-04	MOS	6	11-Oct-24		11-Apr-25		85 d	11-Apr-2025(4)	Service ATA:34
SN:81503	HRS		9913						3.2
	AFL		4664						64.7
									22
REF:									
<b>38-10-00-670-801-01 STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION</b>									
	MOS	6 (+1m)	11-Oct-24		11-Apr-25	11-May-25	85 d (+30)	11-Apr-2025(4)	Service ATA:38
	HRS		9913						3.2
	AFL		4664						64.7
									22
REF: AMM 38-10-00-670-801									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
31-CARS-625-016-00 <sup>U</sup>		FDR ULD RECERTIFICATION&#13;&#10;							
	MOS	12	15-Apr-24		15-Apr-25		89 d	15-Apr-2025(2)	9
	HRS		9887						90.7
	AFL		4656						30
REF:									
315A18 <sup>U</sup>		RECERTIFY FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON							
PN:DK120/90	MOS	12	15-Apr-24		15-Apr-25		89 d	15-Apr-2025(2)	9
SN:AT190134	HRS		9887						90.7
	AFL		4656						30
REF:									
34-CARS-625-010-00 <sup>U</sup>		STANDBY COMPASS SWING&#13;&#10;							
	MOS	12	15-Apr-24		15-Apr-25		89 d	15-Apr-2025(2)	9
	HRS		9887						90.7
	AFL		4656						30
REF:									
342A09 <sup>U</sup>		SWING CHECK STAND-BY COMPASS							
PN:KCA0105W	MOS	12	15-Apr-24		15-Apr-25		89 d	15-Apr-2025(2)	9
SN:AA205	HRS		9887						90.7
	AFL		4656						30
REF:									
342A16 <sup>U</sup>		CHECK STAND-BY HORIZON BATTERY CAPACITY							
PN:501-1228-04	MOS	12	15-Apr-24		15-Apr-25		89 d	15-Apr-2025(2)	9
SN:81503	HRS		9887						90.7
	AFL		4656						30
REF:									
057110		NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION							
	MOS		15-Apr-24					16-Apr-2025(3)	9
	HRS	150 (+100)	9662.9		(9812.9)10037	9912.9	59.3 (+100)		90.7
	ENC		4659						-79
REF: LMM 72-00-00									
057110		NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION							
	MOS		15-Apr-24					16-Apr-2025(3)	9
	HRS	150 (+100)	9860.9		(10010.9)10037	10110.9	59.3 (+100)		90.7
	ENC		4757						81
REF: LMM 72-00-00									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
24-31-17-220-805-03		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 3 STARTER-GENERATOR (R1PA)								Service ATA:24
PN:8060-160	MOS		15-Apr-24					16-Apr-2025(3)	9	
SN:1589	HRS	150	9887		10037		59.3		90.7	
	AFL		4656						30	
REF: AMM 24-31-17-220-805										
057110		NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION								Package ATA:05
	MOS		15-Apr-24					17-Apr-2025(3)	9	
	HRS	150 (+100)	9702.1		(9852.1)10037.8	9952.1	60.1 (+100)		89.9	
	ENC		4652						-79	
REF: LMM 72-00-00										
24-33-05-220-803-01		CHECK OF THE APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (21PA)								Service ATA:24
PN:8060-141-1	MOS		13-Jun-23					19-Apr-2025(3)	19.1	
SN:1160	HRS									
	AFL									
	APH	150 (+3%)	5612.3		5762.3	5766.8	61.5 (+4.5)		88.5	
REF: AMM 24-33-05-220-803										
32-00-00-700-801-01		CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13GA)								Service ATA:32
	MOS	18 (+1m)	31-Oct-23		30-Apr-25	31-May-25	104 d (+31)	30-Apr-2025(2)	14.5	
	HRS		9831.2						146.5	
	AFL		4640						46	
REF: AMM 32-00-00-700-801										
32-00-00-700-801-02		CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA)								Service ATA:32
	MOS	18 (+1m)	31-Oct-23		30-Apr-25	31-May-25	104 d (+31)	30-Apr-2025(2)	14.5	
	HRS		9831.2						146.5	
	AFL		4640						46	
REF: AMM 32-00-00-700-801										
32-00-00-700-801-03		CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA)								Service ATA:32
	MOS	18 (+1m)	31-Oct-23		30-Apr-25	31-May-25	104 d (+31)	30-Apr-2025(2)	14.5	
	HRS		9831.2						146.5	
	AFL		4640						46	
REF: AMM 32-00-00-700-801										
05-08-00-200-800-21		1B INSPECTION								Package ATA:05
	MOS		29-Apr-16					02-May-2025	104.6	
	HRS	1600 (+40)	8447.8		10047.8	10087.8	70.1 (+40)		1529.9	
	AFL		4114						572	
REF: GENERIC NO REF										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
493020		APU - REMOVE AND REPLACE FUEL CONTROL FUEL FILTER ELEMENT							Service	ATA:49
PN:3882730-8	MOS		22-Oct-13					01-Jun-2025	134.8	
SN:20080	HRS	1000	4790.4		5790.4		89.6		910.4	
	APUS									
REF: MM 49-30-52										
21-52-05-610-801-01		TURBOCOOLER OIL SERVICING - TURBOCOOLER (504HN) OIL TOP-UP							Service	ATA:21
	MOS		14-Apr-24					01-Jul-2025(2)	9.1	
	HRS	200	9887		10087		109.3		90.7	
	AFL		4656						30	
REF: AMM 21-52-05-610-801										
25-CARS-625-011-32 <sup>U S</sup>		LIFE RAFT 01 ELT BATTERY REPLACEMENT							Service	ATA:25
	MOS		19-Dec-19		01-Jul-25 (M)		166 d	01-Jul-2025	60.9	
REF:										
35-30-05-350-801-01		RESTORATION OF THE PORTABLE OXYGEN BOTTLE (OVERHAUL) - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)							Service	ATA:35
PN:5600-1C1A-YOE	MOS	60 (+3%)	01-Jul-20		01-Jul-25	25-Aug-25	166 d (+55)	01-Jul-2025	54.5	
SN:124812	HRS									
	AFL									
Disposition: OVERHAUL REF: AMM 35-30-05-350-801										
73-20-01-710-802-01A		OPERATIONAL TEST OF THE NO. 1 ENGINE COMPUTER STAND-BY POWER SUPPLY (MANDATORY 5-40)							Service	ATA:73
	MOS		17-Apr-16					02-Jul-2025	105	
	HRS	1640	8447.8		10087.8		110.1		1529.9	
	AFL		4114						572	
Disposition: MANDATORY 5-40 REF: AMM 73-20-01-710-802										
24-32-09-710-802-02		OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)							Service	ATA:24
PN:100-0540-02	MOS	12 (+3%)	08-Aug-24		08-Aug-25	19-Aug-25	204 d (+11)	08-Aug-2025(2)	5.3	
SN:1644	HRS		9894.2						83.5	
	AFL		4658						28	
REF: AMM 24-32-09-710-802										
24-32-09-710-802-03		OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)							Service	ATA:24
PN:100-0540-02	MOS	12 (+3%)	08-Aug-24		08-Aug-25	19-Aug-25	204 d (+11)	08-Aug-2025(2)	5.3	
SN:1158209	HRS		9890.4						87.3	
	AFL		4657						29	
REF: AMM 24-32-09-710-802										
35-10-05-350-801-01		RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - LH PILOT OXYGEN MASK (L502WH)							Service	ATA:35
PN:MC10-12-100	MOS	72 (+3%)	03-Sep-19		03-Sep-25	07-Nov-25	230 d (+65)	03-Sep-2025	64.4	
SN:22626	HRS									
	AFL									
Disposition: OVERHAUL REF: AMM 35-10-05-350-801										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
057140		NO. 3 ENGINE - 500 TO 850 HOUR INSPECTION								Package ATA:05
	MOS		14-Jan-22					05-Oct-2025	36.1	
	HRS	800 (+50)	9164.7		(9964.7)10150.4	10014.7	172.7 (+50)		627.3	
	ENC		4366						207	
REF: LMM 72-00-00										
33-50-37-960-802-03		DISCARD OF THE EPS BATTERY PACKS - EPS 3 (4LW) BATTERY PACK								Service ATA:33
PN:C734-01-030	MOS	25	08-Sep-23		08-Oct-25		265 d	08-Oct-2025	16.3	
SN:CF35274/29/22	HRS		9823.68						154.02	
	AFL		4638						48	
Disposition: LIFE LIMIT REF: AMM 33-50-37-960-802										
24-32-01-350-801-02		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 2 (R1PE)								Service ATA:24
PN:276CH10	MOS	33 (+3%)	15-Jan-23		15-Oct-25	14-Nov-25	272 d (+30)	15-Oct-2025	24	
SN:V01114	HRS	1700 (+3%)	9719.9	TAC:193.1	11226.8	11277.8	1249.1 (+51)		257.8	
	AFL		4600	TAC:64					86	
Disposition: OVERHAUL REF: AMM 24-32-01-350-801										
720120		NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								Service ATA:72
	MOS		30-Apr-12					26-Oct-2025	152.5	
	HRS	2500 (+100)	7478.7		(9978.7)10164.4	10078.7	186.7 (+100)		2313.3	
	ENC		3696						877	
REF: LMM 72-00-00										
724120		NO. 3 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE								Service ATA:72
PN:3072443-5	MOS		25-May-12					26-Oct-2025	151.7	
SN:5-22151-3796	HRS	2500 (+100)	7478.7		(9978.7)10164.4	10078.7	186.7 (+100)		2313.3	
	ENC		3696						877	
REF: LMM 72-40-04										
SB TFE731-72-3800 R01		NO. 3 ENGINE - TURBINE SECTION - ACCOMPLISH EDDY CURRENT INSPECTION OF SPECIFIC SECOND STAGE LOW PRESSURE TURBINE (LPT2) BLADES, PN 3075424, ON TFE731-4 AND -5 MODEL ENGINES, SERVICE BULLETIN								Bulletin ATA:72
	MOS	-	21-Jun-23					26-Oct-2025	18.8	
	HRS		9618.13		(9978.7)10164.4 (M)		186.7		173.87	
	ENC		4615						-42	
Disposition: CATEGORY 2 REF: BULLETINS										
78-31-00-640-802-01		GREASING OF THE THRUST REVERSER DOOR HINGE PINS								Service ATA:78
	MOS	12 (+1m)	29-Oct-24		29-Oct-25	29-Nov-25	286 d (+31)	29-Oct-2025(2)	2.6	
	HRS	400 (+40)	9929.6		10329.6	10369.6	351.9 (+40)		48.1	
	AFL		4670						16	
REF: AMM 78-31-00-640-802										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
21-52-18-100-801-01		CLEANING OF THE HP WATER SEPARATOR FILTER - HP WATER SEPARATOR (505HN)							Service	ATA:21
	MOS	24 (+1m)	31-Oct-23		31-Oct-25	30-Nov-25	288 d (+30)	31-Oct-2025	14.5	
	HRS	1200 (+40)	9831.2		11031.2	11071.2	1053.5 (+40)		146.5	
	AFL		4640						46	
REF: AMM 21-52-18-100-801										
25-64-13-200-801-01		INSPECTION OF LIFE RAFT - NO. 1 LIFE RAFT							Service	ATA:25
PN:1015FAUL-6C0-1-154	MOS	36 (+3%)	08-Nov-22		08-Nov-25 (M)	10-Dec-25	296 d (+32)	08-Nov-2025	26.3	
SN:10UL-00926	HRS		9596.5						381.2	
	AFL		4562						124	
REF: AMM 25-64-13-200-801										
05-08-00-200-800-05		12 M/800 FH INSPECTION							Package	ATA:05
	MOS	12 (+1m)	28-Nov-24	Adj:-19d	09-Nov-25	09-Dec-25	297 d (+30)	09-Nov-2025(2)	1.6	
	HRS	800 (+40)	9949.8		10749.8	10789.8	772.1 (+40)		27.9	
	AFL		4676						10	
REF: GENERIC NO REF										
05-08-00-200-800-15		12 M INSPECTION							Package	ATA:05
	MOS	12 (+1m)	28-Nov-24	Adj:-19d	09-Nov-25	09-Dec-25	297 d (+30)	09-Nov-2025(2)	1.6	
	HRS		9949.8						27.9	
	AFL		4676						10	
REF: GENERIC NO REF										
05-60-00-200-801-01		BASIC INSPECTION&#13;&#10;							Service	ATA:05
	MOS	12 (+1m)	28-Nov-24	Adj:-18d	10-Nov-25	10-Dec-25	298 d (+30)	10-Nov-2025(2)	1.6	
	HRS	400 (+40)	9949.8		10349.8	10389.8	372.1 (+40)		27.9	
	AFL		4676						10	
REF: AMM 05-60-00-200-801										
05-60-00-200-801-03		BASIC INSPECTION - GROUND SERVICING CHECKS&#13;&#10;							Service	ATA:05
	MOS	12 (+1m)	28-Nov-24	Adj:-18d	10-Nov-25	10-Dec-25	298 d (+30)	10-Nov-2025(2)	1.6	
	HRS	400 (+40)	9949.8		10349.8	10389.8	372.1 (+40)		27.9	
	AFL		4676						10	
REF: AMM 05-60-00-200-801										
26-20-13-960-801-01		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)							Service	ATA:26
PN:861385	MOS	60	12-Nov-20		12-Nov-25		300 d	12-Nov-2025	50.1	
SN:UNKNOWN	HRS									
	AFL									
REF: AMM 26-20-13-960-801										
Disposition: SCRAP										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
26-20-13-960-801-03		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)							Service	ATA:26
PN:861375	MOS	60	12-Nov-20		12-Nov-25		300 d	12-Nov-2025	50.1	
SN:UNKNOWN	HRS									
	AFL									
Disposition: SCRAP		REF: AMM 26-20-13-960-801								
26-20-13-960-801-06		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)							Service	ATA:26
PN:861375	MOS	60	12-Nov-20		12-Nov-25		300 d	12-Nov-2025	50.1	
SN:UNKNOWN	HRS									
	AFL									
Disposition: SCRAP		REF: AMM 26-20-13-960-801								
26-20-13-960-801-08		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB)							Service	ATA:26
PN:861385	MOS	60	12-Nov-20		12-Nov-25		300 d	12-Nov-2025	50.1	
SN:UNKNOWN	HRS									
	AFL									
Disposition: SCRAP		REF: AMM 26-20-13-960-801								
FAA 2008-04-14		OPERATIONAL TEST AND INSPECT OVERWING EMERGENCY EXIT							AD	ATA:52
	MOS	24	14-Nov-23		14-Nov-25		302 d	14-Nov-2025	14.1	
	HRS		9831.2						146.5	
	AFL		4640						46	
Disposition: MANDATORY		REF: AD								
25-64-13-350-801-01		RESTORATION OF THE LIFE RAFT (OVERHAUL) - NO. 1 LIFE RAFT							Service	ATA:25
PN:1015FAUL-6C0-1-154	MOS	36 (+3%)	16-Nov-22		16-Nov-25	18-Dec-25	304 d (+32)	16-Nov-2025	26	
SN:10UL-00926	HRS		9596.5						381.2	
	AFL		4562						124	
		REF: AMM 25-64-13-350-801								
057140		NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION							Package	ATA:05
	MOS		31-Jan-22					23-Nov-2025	35.5	
	HRS	800 (+50)	9158.7		(9958.7)10182.8	10008.7	205.1 (+50)		594.9	
	ENC		4381						199	
		REF: LMM 72-00-00								
057140		NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION							Package	ATA:05
	MOS		31-Jan-22					23-Nov-2025	35.5	
	HRS	800 (+50)	9356.7		(10156.7)10182.8	10206.7	205.1 (+50)		594.9	
	ENC		4479						359	
		REF: LMM 72-00-00								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
24-32-09-960-802-03		DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 2 BATTERY (R12FP)							Service	ATA:24
PN:100-0540-02	MOS	48	25-Nov-21		25-Nov-25		313 d	25-Nov-2025	37.7	
SN:1158209	HRS		9319.8						657.9	
	AFL		4467						219	
Disposition: LIFE LIMIT			REF: AMM 24-32-09-960-802							
231A16 <sup>U</sup>		CHECK COMMUNICATION STAND-BY BATTERY CAPACITY							Service	ATA:23
PN:501-1228-04	MOS	12	28-Nov-24		28-Nov-25		316 d	28-Nov-2025(2)	1.6	
SN:2123A	HRS		9949.8						27.9	
	AFL		4676						10	
			REF:							
24-32-09-710-802-04		OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 3 BATTERY (32FP)							Service	ATA:24
PN:100-0540-02	MOS	12 (+3%)	28-Nov-24		28-Nov-25	08-Dec-25	316 d (+10)	28-Nov-2025(2)	1.6	
SN:1143522	HRS		9949.8						27.9	
	AFL		4676						10	
			REF: AMM 24-32-09-710-802							
315A06 <sup>U</sup>		CHECK FLIGHT DATA (FDR) RECORDER CORRELATION (CARS 625 APP. C)							Service	ATA:31
PN:2100-4043-00	MOS	12	28-Nov-24		28-Nov-25		316 d	28-Nov-2025(2)	1.6	
SN:1672202	HRS		9949.8						27.9	
	AFL		4676						10	
			REF:							
25-CARS-625-011-61 <sup>U</sup>		FIRST AID KIT 01 INSPECTION							Service	ATA:25
	MOS	12	23-Dec-24		31-Dec-25 (M)		349 d	31-Dec-2025	.8	
	HRS		9952.8						24.9	
	AFL		4678						8	
			REF:							
256A56 <sup>U</sup>		INSPECT FIRST AID KIT							Service	ATA:25
PN:509217	MOS	-	23-Dec-24		31-Dec-25 (M)		349 d	31-Dec-2025	.8	
SN:111924005	HRS		9952.8						24.9	
	AFL		4678						8	
			REF:							
24-31-13-350-801-04		RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - APU STARTER-GENERATOR (21PA)							Service	ATA:24
PN:8060-141-1	MOS		14-Dec-16					09-Jan-2026	97.1	
SN:1160	HRS									
	AFL									
	APH	900 (+3%)	5036.5		5936.5	5963.5	235.7 (+27)		664.3	
Disposition: OVERHAUL			REF: AMM 24-31-13-350-801							

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
24-32-01-700-801-01		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 1 (L1PE)							Service	ATA:24
PN:276CH10	MOS	17 (+1m)	21-Aug-24		21-Jan-26	21-Feb-26	370 d (+31)	21-Jan-2026	4.8	
SN:202103856	HRS	850 (+85)	9894.2		10744.2	10829.2	766.5 (+85)		83.5	
	AFL		4658						28	
REF: AMM 24-32-01-700-801										
24-32-01-700-801-02		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 2 (R1PE)							Service	ATA:24
PN:276CH10	MOS	17 (+1m)	27-Sep-24		27-Feb-26	27-Mar-26	407 d (+28)	27-Feb-2026	3.6	
SN:V01114	HRS	850 (+85)	9913		10763	10848	785.3 (+85)		64.7	
	AFL		4664						22	
REF: AMM 24-32-01-700-801										
27-50-00-720-802-01A		FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)							Service	ATA:27
	MOS		14-Apr-16					02-Mar-2026	105.1	
	HRS	1800	8447.8		10247.8		270.1		1529.9	
	AFL		4114						572	
Disposition: MANDATORY 5-40 REF: AMM 27-50-00-720-802										
26-10-00-720-801-05		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)							Service	ATA:26
PN:300119800270-3	MOS	72 (+3%)	05-Mar-20		05-Mar-26	09-May-26	413 d (+65)	05-Mar-2026	58.4	
SN:63158	HRS		9159.6						818.1	
	AFL		4396						290	
REF: AMM 26-10-00-720-801										
26-10-00-720-801-06		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)							Service	ATA:26
PN:300119800270-3	MOS	72 (+3%)	05-Mar-20		05-Mar-26	09-May-26	413 d (+65)	05-Mar-2026	58.4	
SN:65278	HRS		9159.6						818.1	
	AFL		4396						290	
REF: AMM 26-10-00-720-801										
21-20-01-350-801-01		RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - LH FLOW LIMITER (L501HN)							Service	ATA:21
PN:2742A020100	MOS		01-Sep-05					08-Mar-2026	232.5	
SN:170	HRS	4800 (+3%)	5451.8		10251.8	10395.8	274.1 (+144)		4525.9	
	AFL		2600						2086	
Disposition: OVERHAUL REF: AMM 21-20-01-350-801										
21-20-01-350-801-02		RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - RH FLOW LIMITER (R501HN)							Service	ATA:21
PN:2742A020100	MOS		01-Sep-05					08-Mar-2026	232.5	
SN:169	HRS	4800 (+3%)	5451.8		10251.8	10395.8	274.1 (+144)		4525.9	
	AFL		2600						2086	
Disposition: OVERHAUL REF: AMM 21-20-01-350-801										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
32-44-00-250-801-01		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG OUTBOARD WHEEL (L540GC)							Service	ATA:32
PN:C20180410	MOS		20-May-21					20-Mar-2026	43.9	
SN:02867/02984	HRS		9227.5						750.2	
	AFL	400 (+3%)	4427		4827	4839	141 (+12)		259	
REF: AMM 32-44-00-250-801										
32-44-00-250-801-02		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG INBOARD WHEEL (L535GC)							Service	ATA:32
PN:C20180410	MOS		20-May-21					20-Mar-2026	43.9	
SN:01711/01711	HRS		9227.5						750.2	
	AFL	400 (+3%)	4427		4827	4839	141 (+12)		259	
REF: AMM 32-44-00-250-801										
35-10-05-350-801-02		RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - RH PILOT OXYGEN MASK (R502WH)							Service	ATA:35
PN:MC10-12-100	MOS	72 (+3%)	06-Apr-20		06-Apr-26	10-Jun-26	445 d (+65)	06-Apr-2026	57.3	
SN:55146	HRS									
	AFL									
Disposition: OVERHAUL REF: AMM 35-10-05-350-801										
29-20-00-720-801-02		FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - SYSTEM 2							Service	ATA:29
	MOS		31-Jan-05					07-Apr-2026	239.5	
	HRS	5000	5271.2		10271.2		293.5		4706.5	
	AFL		2499						2187	
REF: AMM 29-20-00-720-801										
29-20-03-220-801-01		CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (3ML)							Service	ATA:29
PN:42032	MOS		31-Jan-05					07-Apr-2026	239.5	
SN:AH57456	HRS	5000 (+3%)	5271.2		10271.2	10421.2	293.5 (+150)		4706.5	
	AFL		2499						2187	
REF: AMM 29-20-03-220-801										
32-44-00-250-801-03		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R535GC)							Service	ATA:32
PN:C20180410	MOS		24-Jun-21					11-Apr-2026	42.7	
SN:02509/02593	HRS		9243.8						733.9	
	AFL	400 (+3%)	4434		4834	4846	148 (+12)		252	
REF: AMM 32-44-00-250-801										
27-15-05-350-801-01		RESTORATION OF THE ROLL MAIN AFU (FUNCTIONAL TEST / SERVICING) - ROLL MAIN AFU (523CC)							Service	ATA:27
PN:105124	MOS	144 (+3%)	22-Apr-14		22-Apr-26	31-Aug-26	461 d (+131)	22-Apr-2026	128.8	
SN:88	HRS									
	AFL									
REF: AMM 27-15-05-350-801										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
27-25-05-350-801-01		RESTORATION OF THE YAW MAIN AFU (FUNCTIONAL TEST / SERVICING) - YAW MAIN AFU (573CC)							
PN:105125	MOS	144 (+3%)	22-Apr-14		22-Apr-26	31-Aug-26	461 d (+131)	22-Apr-2026	128.8
SN:82	HRS								
	AFL								
REF: AMM 27-25-05-350-801									
27-35-05-350-801-01		RESTORATION OF THE PITCH MAIN AFU (FUNCTIONAL TEST / SERVICING) - PITCH MAIN AFU (524CW)							
PN:105122-02	MOS	144 (+3%)	22-Apr-14		22-Apr-26	31-Aug-26	461 d (+131)	22-Apr-2026	128.8
SN:78	HRS								
	AFL								
REF: AMM 27-35-05-350-801									
27-80-23-720-801-01		FUNCTIONAL TEST OF THE INBOARD SLAT VALVE BOX - INBOARD SLAT VALVE BOX (507CM)							
PN:108117-05	MOS	144 (+3%)	22-Apr-14		22-Apr-26	31-Aug-26	461 d (+131)	22-Apr-2026	128.8
SN:270	HRS								
	AFL								
REF: AMM 27-80-23-720-801									
27-80-23-720-802-01		FUNCTIONAL TEST OF THE OUTBOARD SLAT VALVE BOX - OUTBOARD SLAT VALVE BOX (517CM)							
PN:108117-06	MOS	144 (+3%)	22-Apr-14		22-Apr-26	31-Aug-26	461 d (+131)	22-Apr-2026	128.8
SN:273	HRS								
	AFL								
REF: AMM 27-80-23-720-802									
27-14-01-350-801-01		RESTORATION OF THE ROLL TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL TRIM ACTUATOR (13CC)							
PN:021057-32	MOS	144 (+3%)	23-Apr-14		23-Apr-26	01-Sep-26	462 d (+131)	23-Apr-2026	128.8
SN:7965	HRS								
	AFL								
REF: AMM 27-14-01-350-801									
27-24-01-350-801-01		RESTORATION OF THE YAW TRIM ACTUATOR (FUNCTIONAL TEST) - YAW TRIM ACTUATOR (3CC)							
PN:021057-28	MOS	144 (+3%)	23-Apr-14		23-Apr-26	01-Sep-26	462 d (+131)	23-Apr-2026	128.8
SN:7964	HRS								
	AFL								
REF: AMM 27-24-01-350-801									
25-62-01-720-801-01		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (900RK)							
PN:DK120	MOS	25 (+3%)	04-Apr-24		04-May-26	27-May-26	473 d (+23)	04-May-2026	9.4
SN:SD17225	HRS		9887						90.7
	AFL		4656						30
REF: AMM 25-62-01-720-801									



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
25-62-01-720-801-02		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)							Service	ATA:25
PN:DK120/90	MOS	25 (+3%)	15-Apr-24		15-May-26	07-Jun-26	484 d (+23)	15-May-2026	9	
SN:AT190134	HRS		9887						90.7	
	AFL		4656						30	
REF: AMM 25-62-01-720-801										
499020		APU - REMOVE AND INSPECT MAGNETIC DRAIN PLUG							Service	ATA:49
	MOS	17	17-Dec-24		17-May-26		486 d	17-May-2026	1	
	HRS	750	5700.8		6450.8		750		0	
	APUS		0						0	
REF: MM 49-90-46										
27-14-03-350-801-01		RESTORATION OF THE ROLL EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL EMERGENCY TRIM ACTUATOR (22CC)							Service	ATA:27
PN:021127	MOS	144 (+3%)	23-May-14		23-May-26	02-Oct-26	492 d (+132)	23-May-2026	127.8	
SN:296	HRS									
	AFL									
REF: AMM 27-14-03-350-801										
26-20-13-960-801-01M		DISCARD NO. 1 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (L3WB) CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:861385	MOS	84	01-Jun-19		01-Jun-26		501 d	01-Jun-2026	67.5	
SN:UNKNOWN	HRS									
	AFL									
Disposition: LIFE LIMIT										
REF: AMM 26-20-13-960-801										
26-20-13-960-801-08M		DISCARD NO. 2 ENGINE FIRST SHOOT RH FIRE EXTINGUISHER PERCUSSION (R6WB) CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:861385	MOS	84	01-Jun-19		01-Jun-26		501 d	01-Jun-2026	67.5	
SN:UNKNOWN	HRS									
	AFL									
Disposition: LIFE LIMIT										
REF: AMM 26-20-13-960-801										
24-32-09-960-802-02		DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 1 BATTERY (L12FP)							Service	ATA:24
PN:100-0540-02	MOS	48	14-Jun-22		14-Jun-26		514 d	14-Jun-2026	31.1	
SN:1644	HRS		9508.6						469.1	
	AFL		4533						153	
Disposition: LIFE LIMIT										
REF: AMM 24-32-09-960-802										
27-25-07-350-801-01		RESTORATION OF THE YAW AUXILIARY AFU (FUNCTIONAL TEST / SERVICING) - YAW AAFU (572CC)							Service	ATA:27
PN:105070-04	MOS	144 (+3%)	19-Jun-14		19-Jun-26	28-Oct-26	519 d (+131)	19-Jun-2026	126.9	
SN:807	HRS		8032						1945.7	
	AFL		3965						721	
REF: AMM 27-25-07-350-801										



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
32-11-00-350-801-01		RESTORATION OF THE MLG LEGS (OVERHAUL) - LH MLG LEG (L2GF)							
PN:D22801100-11/-13-14	MOS	144 (+3%)	19-Jun-14		19-Jun-26	28-Oct-26	519 d (+131)	19-Jun-2026	126.9
SN:U80	HRS		8032						1945.7
	AFL	6000	3965		9965		5279		721
Disposition: OVERHAUL		REF: AMM 32-11-00-350-801							
32-11-00-350-801-02		RESTORATION OF THE MLG LEGS (OVERHAUL) - RH MLG LEG (R2GF)							
PN:D22802100-11/-13-14	MOS	144 (+3%)	19-Jun-14		19-Jun-26	28-Oct-26	519 d (+131)	19-Jun-2026	126.9
SN:U79	HRS		8032						1945.7
	AFL	6000	3965		9965		5279		721
Disposition: OVERHAUL		REF: AMM 32-11-00-350-801							
32-21-00-350-801-01		RESTORATION OF THE NLG LEG (OVERHAUL) - NLG LEG (3GF)							
PN:D22811200-14/-16-X-18-19-/-/22	MOS	144 (+3%)	19-Jun-14		19-Jun-26	28-Oct-26	519 d (+131)	19-Jun-2026	126.9
SN:U79	HRS		8032						1945.7
	AFL	6000	3965		9965		5279		721
Disposition: OVERHAUL		REF: AMM 32-21-00-350-801							
32-22-01-350-801-01		RESTORATION OF THE NLG DRAG BRACE YOKE ASSY (OVERHAUL) - NLG DRAG BRACE (11GA)							
PN:GA62269	MOS	144 (+3%)	19-Jun-14		19-Jun-26	28-Oct-26	519 d (+131)	19-Jun-2026	126.9
SN:438MNR	HRS		8032						1945.7
	AFL	6000	3965		9965		5279		721
Disposition: OVERHAUL		REF: AMM 32-22-01-350-801							
53-10-03-220-801-03C		DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS - DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)							
	MOS	144 (+2m)	19-Jun-14		19-Jun-26	19-Aug-26	519 d (+61)	19-Jun-2026	126.9
	HRS		8032						1945.7
	AFL		3965						721
Disposition: CPCP		REF: AMM 53-10-03-220-801							
53-10-39-220-802-01C		DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							
	MOS	144 (+2m)	19-Jun-14		19-Jun-26	19-Aug-26	519 d (+61)	19-Jun-2026	126.9
	HRS		8032						1945.7
	AFL		3965						721
Disposition: CPCP		REF: AMM 53-10-39-220-802							
32-44-00-250-801-05		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L565GC)							
PN:C20182100	MOS		09-Oct-19					02-Jul-2026	63.2
SN:1345/1341	HRS		9069						908.7
	AFL	500 (+3%)	4361		4861	4876	175 (+15)		325
Disposition: OVERHAUL		REF: AMM 32-44-00-250-801							

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
32-44-00-250-801-06		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R565GC)								Service ATA:32
PN:C20182100	MOS		09-Oct-19					02-Jul-2026	63.2	
SN:01279/01242	HRS		9069						908.7	
	AFL	500 (+3%)	4361		4861	4876	175 (+15)		325	
REF: AMM 32-44-00-250-801										
55-10-33-640-801-01		LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS								Service ATA:55
	MOS	36 (+1m)	07-Jul-23		07-Jul-26	07-Aug-26	537 d (+31)	07-Jul-2026	18.3	
	HRS	600 (+40)	9780.4		10380.4	10420.4	402.7 (+40)		197.3	
	AFL		4619						67	
REF: AMM 55-10-33-640-801										
790120		NO. 1 ENGINE - CHANGE OIL								Service ATA:79
	MOS		12-Nov-20					21-Aug-2026	50.1	
	HRS	1200 (+100)	8936.6		(10136.6)10360.7	10236.6	383 (+100)		817	
	ENC		4295						285	
REF: LMM 72-00-00										
790120		NO. 2 ENGINE - CHANGE OIL								Service ATA:79
	MOS		12-Nov-20					24-Aug-2026	50.1	
	HRS	1200 (+100)	9136.7		(10336.7)10362.8	10436.7	385.1 (+100)		814.9	
	ENC		4393						445	
REF: LMM 72-00-00										
31-54-00-720-803-01		FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES - ALARM TEST								Service ATA:31
	MOS		23-Jun-23					09-Sep-2026	18.8	
	HRS	600 (+40)	9773		10373	10413	395.3 (+40)		204.7	
	AFL		4617						69	
REF: AMM 31-54-00-720-803										
24-31-17-220-804-02		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - ENGINE 2 STARTER-GENERATOR (M1PA)								Service ATA:24
PN:8060-160	MOS		29-Jun-23					20-Sep-2026	18.6	
SN:3660	HRS	600 (+60)	9780.4		10380.4	10440.4	402.7 (+60)		197.3	
	AFL		4619						67	
REF: AMM 24-31-17-220-804										
499040		APU - REMOVE AND REPLACE OIL FILTER ELEMENT								Service ATA:49
	MOS		23-Jun-23					06-Oct-2026	18.8	
	HRS	500 (+20%/-20%)	5614.2		6114.2	6214.2	413.4 (+100)		86.6	
	APUS									
REF: MM 49-90-47										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
<b>499110 APU - SOAP CHECK OIL</b>									
	MOS		23-Jun-23					06-Oct-2026	18.8
	HRS	500 (+20%/-20%)	5614.2		6114.2	6214.2	413.4 (+100)		86.6
	APUS								
REF: SIL SIL APU-49									
<b>28-70-13-720-802-01 FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L509QD)</b>									
PN:B06GA1051	MOS		19-Jul-05					01-Nov-2026	233.9
SN:607	HRS	5000	5408.1		10408.1		430.4		4569.6
	AFL		2579						2107
REF: AMM 28-70-13-720-802									
<b>05-08-00-200-800-07 36 M/2400 FH INSPECTION</b>									
	MOS	36 (+1m)	09-Nov-23		09-Nov-26	09-Dec-26	662 d (+30)	09-Nov-2026	14.2
	HRS	2400 (+40)	9831.2		12231.2	12271.2	2253.5 (+40)		146.5
	AFL		4640						46
REF: GENERIC NO REF									
<b>05-08-00-200-800-17 36 M INSPECTION</b>									
	MOS	36 (+1m)	11-Nov-23		11-Nov-26	11-Dec-26	664 d (+30)	11-Nov-2026	14.2
	HRS		9831.2						146.5
	AFL		4640						46
REF: GENERIC NO REF									
<b>05-08-00-200-800-06 24 M/1600 FH INSPECTION</b>									
	MOS	24 (+1m)	28-Nov-24	Adj:-16d	12-Nov-26	12-Dec-26	665 d (+30)	12-Nov-2026	1.6
	HRS	1600 (+40)	9949.8		11549.8	11589.8	1572.1 (+40)		27.9
	AFL		4676						10
REF: GENERIC NO REF									
<b>05-08-00-200-800-16 24 M INSPECTION</b>									
	MOS	24 (+1m)	28-Nov-24	Adj:-16d	12-Nov-26	12-Dec-26	665 d (+30)	12-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
REF: GENERIC NO REF									
<b>05-08-00-200-800-31 1C INSPECTION</b>									
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1
	HRS		9182.3						795.4
	AFL	3750	4405		8155		3469		281
REF: GENERIC NO REF									



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
05-08-00-200-800-32		2C INSPECTION							
	MOS	144 (+2m)	19-Jun-14	Adj:146d	12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	Package 126.9 ATA:05
	HRS		8032						1945.7
	AFL	7500	3965	Adj:-3310	8155		3469		721
REF: GENERIC NO REF									
05-50-00-910-801-01		AIRCRAFT CHECK FLIGHT							
	MOS	72 (+2m)	19-Jun-14		12-Nov-26 (M)	12-Jan-27	665 d (+61)	12-Nov-2026	Service 126.9 ATA:05
	HRS		8032						1945.7
	AFL	3750	3965		8155 (M)		3469		721
REF: AMM 05-50-00-910-801									
27-40-01-210-802-01		VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)							
PN:021121-11	MOS	72 (+3%)	12-Nov-20		12-Nov-26	16-Jan-27	665 d (+65)	12-Nov-2026	Service 50.1 ATA:27
SN:202	HRS		9182.3						795.4
	AFL	3750 (+3%)	4405		8155	8267.5	3469 (+112.5)		281
REF: AMM 27-40-01-210-802									
32-11-00-220-801-01		DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF)							
PN:D22801100-11/-13-14	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	Service 50.1 ATA:32
SN:U80	HRS		9182.3						795.4
	AFL		4405						281
REF: AMM 32-11-00-220-801									
32-11-00-220-801-02		DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF)							
PN:D22802100-11/-13-14	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	Service 50.1 ATA:32
SN:U79	HRS		9182.3						795.4
	AFL		4405						281
REF: AMM 32-11-00-220-801									
32-11-25-220-801-01		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)							
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	Service 50.1 ATA:32
	HRS		9182.3						795.4
	AFL		4405						281
REF: AMM 32-11-25-220-801									
32-11-25-220-801-02		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)							
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	Service 50.1 ATA:32
	HRS		9182.3						795.4
	AFL		4405						281
REF: AMM 32-11-25-220-801									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
32-11-25-220-801-03		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)							Service	ATA:32
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
REF: AMM 32-11-25-220-801										
32-11-25-220-801-04		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)							Service	ATA:32
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
REF: AMM 32-11-25-220-801										
32-21-00-220-801-01		DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF)							Service	ATA:32
PN:D22811200-14-/-16-X-18-19-/-22	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	50.1	
SN:U79	HRS		9182.3						795.4	
	AFL		4405						281	
REF: AMM 32-21-00-220-801										
32-21-09-220-801-01		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING							Service	ATA:32
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
REF: AMM 32-21-09-220-801										
32-21-09-220-801-02		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING							Service	ATA:32
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
REF: AMM 32-21-09-220-801										
32-21-09-220-801-03		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING							Service	ATA:32
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
REF: AMM 32-21-09-220-801										
32-21-09-220-801-04		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING							Service	ATA:32
	MOS	72 (+8m)	12-Nov-20		12-Nov-26	12-Jul-27	665 d (+242)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
REF: AMM 32-21-09-220-801										

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
53-00-00-220-801-01C		DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP			REF: AMM 53-00-00-220-801							
53-10-00-210-802-01		GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT							Service	ATA:53
	MOS	24 (+1m)	28-Nov-24	Adj:-16d	12-Nov-26	12-Dec-26	665 d (+30)	12-Nov-2026	1.6	
	HRS	4000	9949.8		13949.8		3972.1		27.9	
	AFL		4676						10	
			REF: AMM 53-10-00-210-802							
53-10-00-220-802-01C		DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP			REF: AMM 53-10-00-220-802							
53-10-39-220-801-01C		DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP			REF: AMM 53-10-39-220-801							
53-30-00-220-801-01C		DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP			REF: AMM 53-30-00-220-801							
53-40-00-220-801-01C		DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP			REF: AMM 53-40-00-220-801							
53-40-00-220-802-01C		DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP			REF: AMM 53-40-00-220-802							

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
53-40-00-270-801-01C		ULTRASONIC-INSPECTION FOR CORROSION AROUND THE FASTENERS OF THE FRONT CENTER PANEL AHEAD OF FRAME 10 (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP		REF: AMM 53-40-00-270-801								
53-50-00-220-803-01C		DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							Service	ATA:53
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP		REF: AMM 53-50-00-220-803								
55-00-00-210-801-01		GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT							Service	ATA:55
	MOS	24 (+1m)	28-Nov-24	Adj:-16d	12-Nov-26	12-Dec-26	665 d (+30)	12-Nov-2026	1.6	
	HRS	4000	9949.8		13949.8		3972.1		27.9	
	AFL		4676						10	
Disposition: CPCP		REF: AMM 55-00-00-210-801								
55-00-00-220-801-01C		DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)							Service	ATA:55
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP		REF: AMM 55-00-00-220-801								
57-00-00-210-801-01		GENERAL VISUAL INSPECTION OF THE WINGS - LH WING							Service	ATA:57
	MOS	24 (+1m)	28-Nov-24	Adj:-16d	12-Nov-26	12-Dec-26	665 d (+30)	12-Nov-2026	1.6	
	HRS	4000	9949.8		13949.8		3972.1		27.9	
	AFL		4676						10	
Disposition: CPCP		REF: AMM 57-00-00-210-801								
57-00-00-210-801-02		GENERAL VISUAL INSPECTION OF THE WINGS - RH WING							Service	ATA:57
	MOS	24 (+1m)	28-Nov-24	Adj:-16d	12-Nov-26	12-Dec-26	665 d (+30)	12-Nov-2026	1.6	
	HRS	4000	9949.8		13949.8		3972.1		27.9	
	AFL		4676						10	
Disposition: CPCP		REF: AMM 57-00-00-210-801								
57-00-00-220-802-01C		DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)							Service	ATA:57
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP		REF: AMM 57-00-00-220-802								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued	
57-00-00-220-802-02C		DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)								
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP		REF: AMM 57-00-00-220-802								
57-10-00-290-801-01C		BORESCOPE INSPECTION OF THE WING TANKS (CPCP)								
	MOS	72 (+2m)	12-Nov-20		12-Nov-26	12-Jan-27	665 d (+61)	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL		4405						281	
Disposition: CPCP		REF: AMM 57-10-00-290-801								
FAA 1999-25-09 PARA (B) & (C)		ACCOMPLISH							AD	ATA:27
	MOS	72	12-Nov-20		12-Nov-26		665 d	12-Nov-2026	50.1	
	HRS		9182.3						795.4	
	AFL	3750	4405		8155		3469		281	
Disposition: MANDATORY		REF: AD								
34-14-01-700-881-01		TEST NO. 1 AIR DATA (ADC1) COMPUTER (FAR 91.411)								
PN:7000700-647	MOS	24	28-Nov-24		13-Nov-26		666 d	13-Nov-2026	1.6	
SN:86081720	HRS		9949.8						27.9	
	AFL		4676						10	
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411								
34-14-01-700-881-02		TEST NO. 2 AIR DATA (ADC 2) COMPUTER (FAR 91.411)								
PN:7000700-647	MOS	24	28-Nov-24		13-Nov-26		666 d	13-Nov-2026	1.6	
SN:89123755	HRS		9949.8						27.9	
	AFL		4676						10	
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411								
34-15-02-700-881-01		TEST PILOT STAND-BY ALTIMETER (FAR 91.411)								
PN:64141-530-1	MOS	24	28-Nov-24		13-Nov-26		666 d	13-Nov-2026	1.6	
SN:3585	HRS		9949.8						27.9	
	AFL		4676						10	
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411								
34-54-00-700-881-01		TEST NO. 1 ATC TRANSPONDER (FAR 91.413)								
PN:622-9210-501	MOS	24	28-Nov-24		13-Nov-26		666 d	13-Nov-2026	1.6	
SN:4V32V	HRS		9949.8						27.9	
	AFL		4676						10	
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.413								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
34-54-00-700-881-02		TEST NO. 2 ATC TRANSPONDER (FAR 91.413)							Service ATA:34
PN:622-9210-501	MOS	24	28-Nov-24		13-Nov-26		666 d	13-Nov-2026	1.6
SN:4V32X	HRS		9949.8						27.9
	AFL		4676						10
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.413							
53-00-00-210-801-01C		GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION (CPCP)							Service ATA:53
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 53-00-00-210-801							
53-11-00-210-801-02C		GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)							Service ATA:53
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 53-11-00-210-801							
53-41-00-220-801-01C		DETAILED INSPECTION OF THE UPPER LH WING ROOT BOLT RECESSES (CPCP)							Service ATA:53
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 53-41-00-220-801							
53-41-00-220-801-02C		DETAILED INSPECTION OF THE UPPER RH WING ROOT BOLT RECESSES (CPCP)							Service ATA:53
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 53-41-00-220-801							
53-50-00-220-805-02C		DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)							Service ATA:53
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 53-50-00-220-805							
55-00-00-210-801-01C		GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)							Service ATA:55
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 55-00-00-210-801							



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
57-00-00-210-801-01C		GENERAL VISUAL INSPECTION OF THE WINGS - LH WING (CPCP)							
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 57-00-00-210-801							
57-00-00-210-801-02C		GENERAL VISUAL INSPECTION OF THE WINGS - RH WING (CPCP)							
	MOS	24 (+1m)	28-Nov-24	Adj:-12d	16-Nov-26	16-Dec-26	669 d (+30)	16-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP		REF: AMM 57-00-00-210-801							
26-20-09-350-801-02		RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)							
PN:861630	MOS	60	19-Nov-21		19-Nov-26		672 d	19-Nov-2026	37.9
SN:24708	HRS								
	AFL								
Disposition: MANDATORY		REF: AMM 26-20-09-350-801							
26-20-09-350-801-05		RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)							
PN:861630	MOS	60	19-Nov-21		19-Nov-26		672 d	19-Nov-2026	37.9
SN:55569	HRS								
	AFL								
Disposition: MANDATORY		REF: AMM 26-20-09-350-801							
26-20-09-350-801-03		RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)							
PN:861630	MOS	60	24-Nov-21		24-Nov-26		677 d	24-Nov-2026	37.7
SN:22914	HRS								
	AFL								
Disposition: MANDATORY		REF: AMM 26-20-09-350-801							
34-01-00-720-801-01		FUNCTIONAL TEST OF THE EFIS SYSTEM							
	MOS	24 (+1m)	28-Nov-24		28-Nov-26	28-Dec-26	681 d (+30)	28-Nov-2026	1.6
	HRS	1600 (+40)	9949.8		11549.8	11589.8	1572.1 (+40)		27.9
	AFL		4676						10
		REF: AMM 34-01-00-720-801							
34-16-00-720-801-01		FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 1 (L2FX)							
PN:7000700-647	MOS	24 (+3%)	28-Nov-24		28-Nov-26	19-Dec-26	681 d (+21)	28-Nov-2026	1.6
SN:86081720	HRS		9949.8						27.9
	AFL		4676						10
		REF: AMM 34-16-00-720-801							

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



# Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
<b>34-16-00-720-801-02 FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 2 (R2FX)</b>									
PN:7000700-647	MOS	24 (+3%)	28-Nov-24		28-Nov-26	19-Dec-26	681 d (+21)	28-Nov-2026	1.6
SN:89123755	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 34-16-00-720-801									
<b>34-16-00-720-801-03 FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY ALTIMETER (1FK)</b>									
PN:64141-530-1	MOS	24 (+3%)	28-Nov-24		28-Nov-26	19-Dec-26	681 d (+21)	28-Nov-2026	1.6
SN:3585	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 34-16-00-720-801									
<b>34-16-00-720-801-04 FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY MACH AIRSPEED INDICATOR (26FL)</b>									
PN:64032-229-1	MOS	24 (+3%)	28-Nov-24		28-Nov-26	19-Dec-26	681 d (+21)	28-Nov-2026	1.6
SN:1678	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 34-16-00-720-801									
<b>34-54-00-720-802-01 FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM PERIODIC TESTS</b>									
PN:622-9210-501	MOS	24 (+3%)	28-Nov-24		28-Nov-26	19-Dec-26	681 d (+21)	28-Nov-2026	1.6
SN:4V32V	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 34-54-00-720-802									
<b>34-54-00-720-802-02 FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM PERIODIC TESTS</b>									
PN:622-9210-501	MOS	24 (+3%)	28-Nov-24		28-Nov-26	19-Dec-26	681 d (+21)	28-Nov-2026	1.6
SN:4V32X	HRS		9949.8						27.9
	AFL		4676						10
REF: AMM 34-54-00-720-802									
<b>34-CARS-625-013-01<sup>U</sup> ALTIMETER DEVICES NO.1 SYSTEM</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
REF:									
<b>34-CARS-625-013-02<sup>U</sup> ALTIMETER DEVICES NO.2 SYSTEM</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
REF:									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
<b>34-CARS-625-013-05 U STANDBY ALTIMETER DEVICES&amp;#13;&amp;#10;</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
				REF:					
<b>34-CARS-625-014-01 U ATC TRANSPONDERS NO.1 SYSTEM&amp;#13;&amp;#10;</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
				REF:					
<b>34-CARS-625-014-02 U ATC TRANSPONDERS NO.2 SYSTEM&amp;#13;&amp;#10;</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
				REF:					
<b>341TC1 U PERFORM PILOT ALTIMETRY SYSTEM 24 MONTH RE-CERTIFICATION AS PER CAR 625 APPENDIX C</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: RVSM				REF:					
<b>341TC2 U PERFORM CO-PILOT ALTIMETRY SYSTEM 24 MONTH RE-CERTIFICATION AS PER CAR 625 APPENDIX C</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: RVSM				REF:					
<b>341TC3 U PERFORM STANDBY ALTIMETRY SYSTEM 24 MONTH RE-CERTIFICATION AS PER CAR 625 APPENDIX C</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: RVSM				REF:					
<b>341TC4 U PERFORM #1 TRANSPONDER 24 MONTH RE-CERTIFICATION AS PER CAR 625 APPENDIX C</b>									
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: RVSM				REF:					

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: FALCON 900 Serial: 075 RegNo: C-GEOS HRS: 9977.7 AFL: 4686 As Of: 16-Jan-2025 Operator: SKYSERVICE BUSINESS AVIATION INC.

Report Date: 16-Jan-2025

PN & SN	Unit	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	Time Accrued
341TC5 U		PERFORM #2 TRANSPONDER 24 MONTH RE-CERTIFICATION AS PER CAR 625 APPENDIX C							
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: RVSM			REF:						
52-20-00-610-801-01A		SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40)							
	MOS	24	28-Nov-24		28-Nov-26		681 d	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: MANDATORY 5-40			REF: AMM 52-20-00-610-801						
53-40-00-210-802-01		GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS							
	MOS	24 (+1m)	28-Nov-24		28-Nov-26	28-Dec-26	681 d (+30)	28-Nov-2026	1.6
	HRS	4000	9949.8		13949.8		3972.1		27.9
	AFL		4676						10
			REF: AMM 53-40-00-210-802						
53-50-00-210-806-01C		GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							
	MOS	24 (+1m)	28-Nov-24		28-Nov-26	28-Dec-26	681 d (+30)	28-Nov-2026	1.6
	HRS		9949.8						27.9
	AFL		4676						10
Disposition: CPCP			REF: AMM 53-50-00-210-806						
25-64-17-900-803-06		NO. 6 PASSENGER LIFE VEST							
PN:P01074-101	MOS	O/C	01-Feb-23		30-Nov-26 (M)		683 d	30-Nov-2026	23.5
SN:23020490836	HRS								
	AFL								
			REF: AMM GENERIC 1						
25-60-00-200-801-03		INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT&#13;&#10;							
	MOS	DUE	23-Dec-24		23-Dec-26 (M)		706 d	23-Dec-2026	.8
	HRS		9952.8						24.9
	AFL		4678						8
			REF: AMM 25-60-00-200-801						
33-50-37-960-802-02		DISCARD OF THE EPS BATTERY PACKS - EPS 2 (R3LW) BATTERY PACK							
PN:C734-01-030	MOS	25	13-Dec-24		13-Jan-27		727 d	13-Jan-2027	1.1
SN:CF37607/10/24	HRS		9952.1						25.6
	AFL		4678						8
Disposition: LIFE LIMIT			REF: AMM 33-50-37-960-802						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time